

CNC CAT




### CNC CAT router Systems Plasma and Engravers


LCD Display CO2 Current Meter for 100W &150W Power Supply Adjustable Current. Externally connected to the power supply of 00W &150W with network port through network cable, real-time display of processing current and information status.



# LCD Function



# Application



**Turn this switch to the left:** The LCD trimmer potentiometer does not work, and the LCD displays normally.

**Turn this switch to the right:** The LCD comes with a trimmer potentiometer to adjust the current.